

147634

12. Chemical Recovery Systems, Inc.  
142 Locust  
Elyria, Ohio

10-22-79

13. Laskin Waste Oil Service  
717 North Poplar Street  
Jefferson, Ohio

## Cleveland Metropolitan Area

## Inspection Activity

<u>Site Name &amp; Location</u>	<u>Inspection Information</u>
14. Mr. Webb Mill St. and Station Rock Creek, OH	S&A to inspect
15. Union Lake Lagoon Middle Road Ashtabula, OH	OEPA inspected
16. Detrex Chemical Industries, Inc. Ashtabula, OH	Sampling survey conducted by EDO
17. IMC Chemical Group Ashtabula, OH	Assigned to FIT
18. G&W Natural Resources Middle and State Ashtabula, OH	EDO inspected 3/26/80
19. Landfill 750 Bacan Painesville, OH	OEPA 1-30-80
20. McGean Chemical Corp. E. 29th Street Newburgh Heights, OH	NRC and EPA are investigating

12. Chemical Recovery Systems, Inc.  
142 Locust  
Elyria, Ohio

10-22-79

13. Laskin Waste Oil Service  
717 North Poplar Street  
Jefferson, Ohio

Cleveland Metropolitan Area

Inspection Activity

Site Name & Location

Inspection Information

14. Mr. Webb  
Mill St. and Station  
Rock Creek, OH

S&A to inspect

15. Union Carbide Lagoon  
Middle Road  
Ashtabula, OH

*same as 141*

OEPA inspected

*do fly drive by*

16. Detrex Chemical Industries, Inc.  
Ashtabula, OH

Sampling survey conducted  
by EDO

17. IMC Chemical Group  
Ashtabula, OH

Assigned to FIT

18. G&W Natural Resources  
Middle and State  
Ashtabula, OH

EDO inspected 3/26/80

19. Landfill  
750 Bacan  
Painesville, OH

OEPA 1-30-80

20. McGean Chemical Corp.  
E. 29th Street  
Newburgh Heights, OH

NRC and EPA are investigating